	STATE OF WASHINGT	.O'		
-31 N	DEPARTMENT OF CONSER AND DEVELOPMENT	VATION	#700l	
ell N			# 1004 <b>十 495</b> 9	Z
WELL	May 27 , 196h ;	194 A-F		
	by Driller Driller's Record	-		-
Source	Driller's Record			ł
Locatio	n State of WASHINGTON	<del>  3</del> 5		-
Co	unty Island			l
Ar	ea -		9	1
Ma	p			
	14 14 sec 33 T.33 N, R 1 E. E.	Diagram of		
Drilling	Co Island Well Drillin	g Compan	Ā	
_	dress Freeland, Washington			
Me	thod of Drilling Cable Date	June 17	, 19 5	8
Owner	Hillcrest Village Water Com			
	dress 204 Loerland Lance, Oak H			
			AA	
Land s		grad		
CORRE-	Old (EST Merea By	THICKNESS	DEPTH	-
LATION	Materi 4L	(feet)	(feet)	
If mater	nscribe driller's terminology literally but paraphrase a lal water bearing so state and record struct level if red disurface datum unless otherwise indicated. Correlate Following log of materials list all casings performing the control of the results.	ported Give d	lepths in fee	et.
		+	~	_
	Gravel and hardpan	0	85	_
	Silt	85	91	_
	Brown and clue clay	91	151	-
	Hardpan	151	177	
	Brown clay	177	187	-
	Fine sand, w/bearing	187	221	_
	Casing: 6" from 0 to 197:	<del> </del>	ļ	_
	No perforations	<u> </u>		-
	Screened from 197 to 221	<del> </del>		-
	SWL: 163 on June 15, 1964			-
	171° on May 17, 1958			_
	Eailer Test: 50 gpm with 2'6"	DD after	L hor	Ų
	1 minute recovery time			_
	1 minute recovery time May 17, 1958			-

Sheet

of

sheets

Turn up